

VIA HAND DELIVERY & ELECTRONIC MAIL

January 27, 2023

Emma Rodvien, Coordinator
Energy Facility Siting Board
89 Jefferson Boulevard
Warwick, RI 02888

**Re: SB-2022-01 V148S 115kV Transmission Line
Asset Condition Refurbishment Project (“Project”)
Updates to Proposed Pole Locations**

Dear Emma:

During the initial phases of construction, representatives of The Narraganset Electric Company (the “Company”) met with abutters in advance of starting the structure work for the Project. As a result of these meetings the Company learned that there were three proposed structure locations that abutters desire to be moved due to their location in their respective yards. After a review of the requests with engineering, the Company agreed to adjust the location of the three structures.

The changes are as follows:

New Structure 13 moved approximately 12 feet to the west and away from the maintained lawn space (per the homeowner’s request). Based on this change, the structure height increased approximately 4 feet from the original design (total difference in height change from existing to new is approximately 10-12 feet). The original location for Structure 13 was east of old Structure 219 (see Siting Report Figures Page 5 of 17). Structure 13 is now located west of old Structure 219.

New Structure 16 moved east approximately 18 feet closer to the road and away from the maintained lawn space (per the homeowner’s request). There was no change in height from the original design plan. The original location for Structure 16 was west of old

Emma Rodvien, Coordinator
Energy Facility Siting Board
January 27, 2023
Page 2

Structure 222 (see Siting Report Figures Page 6 of 17). Structure 16 is now located east of old Structure 222 and closer to Great Meadows Lane.

New Structure 43 moved east approximately 7 feet closer to the road and away from an existing shed (per the homeowner's request). There is no change in height from the original design plan. The original location for Structure 43 was west of old Structure 29 (see Siting Report Figures Pages 13 and 14 of 17). Structure 43 is now located east of old Structure 29 and closer to High Street/Diamond Hill Road.

One additional structure was relocated at the recommendation of Company engineers and real estate representatives; this relocation was done in agreement with the owner.

New Structure 32 moved west approximately 40 feet further from the road and away from the embankment along Riverview Drive. There is no change in height from the original design plan. The original proposed location for Structure 32 was to the west of old Structure 19 (see Siting Report Figures Page 11 of 17). Structure 32 was installed further west of the original proposed location.

Please contact me with any questions.

Sincerely,



George W. Watson III

Enclosures

Copy to: Docket No. SB-2022-01