

# FindTheData

by GRAPHIQ

< See All EPA Regulated Facilities



Details CAA CWA RCRA Related

## Ocean State Power Plant - EPA Regulated Facility Harrisville, RI

See all EPA Regulated Facilities

∨ Details

Share


Ocean State Power Plant is located at 1575 Sherman Farm Rd in Harrisville, RI and has had serious violation(s) over the past three years.

- 10 quarter(s) of Clean Air Act violations
- 3 quarter(s) of Clean Water Act violations
- 

There is a population of 229 people (2% minorities) within a 3 mile radius of the facility. The last inspection of Ocean State Power Plant took place 146 days ago.


### Facility Information

<b>Name</b>	<b>Ocean State Power Plant</b>
<b>Address</b>	1575 Sherman Farm Rd Harrisville, Rhode Island 02830
	<a href="#">Get Directions</a>
<b>County</b>	Providence



Population within 3 Mile Radius 229

Minorities within 3 Mile Radius 2%



Enforcement and Compliance History

Current Compliance Status Serious Violation(s)

Days Since Last Inspection 146

Major Yes

Three Year Compliance Status - Last 12 Quarters

- Q1:
Q2:
Q3: Violation/Non-compliance
Q4: Violation/Non-compliance
Q5: Violation/Non-compliance
Q6: Violation/Non-compliance
Q7: Violation/Non-compliance
Q8: Violation/Non-compliance
Q9: Violation/Non-compliance
Q10: Significant Non-compliance
Q11: Significant Non-compliance
Q12: Significant Non-compliance

Compliance Report Compliance Report (epa-echo.gov)

ADVERTISEMENT

Clean Air Act

Share

Clean Air Act

Permit Type Major

NAICS Codes 221112

SIC Codes 4911

Current Compliance Status Violation(s)

<b>Days Since Last Inspection</b> ⓘ	146
<b>Inspections over last 5 years</b> ⓘ	3
<b>Informal Enforcement Actions over last 5 years</b> ⓘ	1
<b>Non-compliant Quarters over last 3 years</b> ⓘ	10

#### Three Year Compliance Status - Last 12 Quarters

- Q1:
- Q2:
- Q3: Violation/Non-compliance
- Q4: Violation/Non-compliance
- Q5: Violation/Non-compliance
- Q6: Violation/Non-compliance
- Q7: Violation/Non-compliance
- Q8: Violation/Non-compliance
- Q9: Violation/Non-compliance
- Q10: Violation/Non-compliance
- Q11: Violation/Non-compliance
- Q12: Violation/Non-compliance

ADVERTISEMENT

∨ Clean Water Act

 Share

Clean Water Act

**SIC Codes** ⓘ 4911

**Current Compliance Status** Serious Violation(s)

**Non-compliant Quarters over last 3 years** ⓘ 3

#### Three Year Compliance Status - Last 12 Quarters

- Q1:
- Q2:
- Q3:
- Q4:
- Q5:

- Q6:
- Q7:
- Q8:
- Q9:
- Q10: Significant Non-compliance
- Q11: Significant Non-compliance
- Q12: Significant Non-compliance

**Non-compliance report - Last 12 Quarters**

- Q1:
- Q2:
- Q3:
- Q4:
- Q5:
- Q6:
- Q7:
- Q8:
- Q9:
- Q10: Reporting violation - non-receipt of DMR
- Q11: Reporting violation - non-receipt of DMR
- Q12: Reporting violation - non-receipt of DMR

ADVERTISEMENT

∨ Resource Conservation and Recovery Act

 Share

<b>Permit Type</b> ⓘ	Small Quantity Generator
<b>Current Compliance Status</b>	No Violations
<b>Days Since Last Inspection</b> ⓘ	3,572

ADVERTISEMENT

∨ Nearby EPA Sites

 Share

Other Harrisville EPA Sites

Name	Address	Current Compliance Status
Uniplast Films Inc	770 Douglas Pike	No Violations

∨ References

---

Data Sources

Source: U.S. Environmental Protection Agency

---

About

Journalist Solutions

Enterprise Solutions

Researcher Solutions

Advertiser Solutions

About Us

Careers

Contact Us

---

© 2016 Graphiq Inc. All Rights Reserved.

[Terms](#) [Privacy](#) [Ad Choices and Cookie Policy](#)

years Ocean State Power's charitable giving will total \$2.4 million. There have been a few problems with the plant over the years. In 1994, a backup oil storage tank leaked 9,700 gallons from a million-gallon storage tank. In March 1994, a muriatic (hydrochloric) acid spill caused the formation of a vapor cloud, which led to the evacuation of about 50 people in nearby homes. During the drought of 1997, an Uxbridge trucking company was fined for illegally taking water out of a local Uxbridge reservoir, causing neighboring wells to go dry. The water was being drained to help meet OSP's high daily water demand.